



### State of Utah

### Department of **Natural Resources**

MICHAEL R. STYLER Executive Director

## Division of Oil, Gas & Mining

JOHN R. BAZA Division Director JON M. HUNTSMAN, JR. Governor

> GARY R. HERBERT Lieutenant Governor

Representatives Present During the Inspection:					
Company	Dennis Ware Controller				
OGM Steve Demczak Environmental Scientist III					

# **Inspection Report**

Permit Number:	C0070006			
Inspection Type:	PARTIAL			
Inspection Date:	Tuesday, December 16, 2008			
Start Date/Time:	12/16/2008 2:00:00 PM			
End Date/Time:	12/16/2008 4:00:00 PM			
Last Inspection:	Wednesday November 12, 2008			

Inspector: Steve Demczak, Environmental Scientist III

Weather: Cold, Sunny, 4 inches of snow cover

InspectionID Report Number: 1868

Accepted by: jhelfric

1/7/2009

Permitee: PLATEAU MINING CORP Operator: PLATEAU MINING CORP

Site: STAR POINT MINE

Address: PO BOX 30, HELPER UT 84526-0030

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: RECLAIMED

<b>Total Permitted</b>		
<b>Total Disturbed</b>	113.34	
Phase I	113.34	
Phase II		
Phase III		

**Current Acreages** 

**Mineral Ownership** 

✓ State

**Types of Operations** ✓ Federal ✓ Underground Surface County Loadout

Processing ☐ Other Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

No violations were issied.

Inspector's Signature:

Steve Demczak, Environmental Scientist III

**Date** 

Monday, November 17, 2008

Inspector ID Number: 39

Permit Number: C0070006 Inspection Type: PARTIAL

Inspection Date: Tuesday, December 16, 2008

Page 2 of 3

#### REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- Substantiate the elements on this inspection by checking the appropriate performance standard.
  For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
  - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers	<b>✓</b>		✓	
3.	Topsoil	<b>✓</b>		✓	
4.a	Hydrologic Balance: Diversions	<b>✓</b>		<b>✓</b>	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments				
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments				
8.	Noncoal Waste				
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage	<b>V</b>		✓	
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading	<b>V</b>		<b>✓</b>	
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.8	a Roads: Construction, Maintenance, Surfacing	✓		✓	
16.k	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0070006 Inspection Type: PARTIAL

Inspection Date: Tuesday, December 16, 2008

Page 3 of 3

#### 2. Signs and Markers

The identification signs at the mine was inspected and contained the correct information required in the R645 Coal Rules.

#### 3. Topsoil

All topsoil was used in reclamation of the site.

## 4.a Hydrologic Balance: Diversions

Diversions were covered with snow.

## 10. Slides and Other Damage

No slides were noticed during the inspection.

## 12. Backfilling And Grading

The mine site is completely backfilled and graded.

## 16.a Roads: Construction, Maintenance, Surfacing

We were unable to make to the top of the hill due to snow cover.